



# DISTRIBUTION POLE REINFORCEMENT #DPR48S & #DPR72S

(PATENTED)

www.polelifesystems.com

**FOR DISTRIBUTION POLE DAMAGE  
CAUSED BY WOODPECKERS, CRACKING,  
AUTO ACCIDENTS, ETC.**

**8" to 11" Diameter Wood Poles**

- Distribution Wood Poles – A 2-Part 1/8" galvanized steel reinforcement installed over the damaged area which brings the pole back to almost full strength. This prevents total pole replacement for large scale woodpecker, storm, auto damage. No foam, wrap or glue required.

**Bolts and Hardware not included.**

Weight per part ½ set:

Hardware Required:

DPR48S: 31 lbs. each

DPR48S: (8) 5/8" bolts/flat washers

DPR72S: 46 lbs. each

DPR72S: (12) 5/8" bolts/flat washers

