

May 1, 2021



www.polelifesystems.com

FOR DISTRIBUTION SCALE POLE DAMAGE CAUSED BY WOODPECKERS, CRACKING, AUTO ACCIDENTS, ETC.

8" to 11" Diameter Wood Poles

- **Distribution Wood Poles** – A 2-Part 1/8" galvanized steel reinforcement installed over the damaged area which brings the pole back to almost full strength. This prevents total pole replacement for large scale woodpecker, storm, auto damage. No foam, wrap or glue required.

Bolts and Hardware not included.

Weight per part ½ set:

DPR48S: 31 lbs. each

DPR72S: 46 lbs. each

Hardware Required:

DPR48S: (8) 5/8" bolts/flat washers

DPR72S: (12) 5/8" bolts/flat washers

DISTRIBUTION POLE REINFORCEMENT #DPR48S & #DPR72S

(PATENTED)

